

Dear Users,

We hereby wish to inform you that the new release of standard application for Standard Air-conditioners is now officially available.

FLSTDmMCZ0E 3.5

In the new official release the AL 50 and AL59 High Superheat Alarm on circuit 1 & 2 will not stop the compressor anymore.

**NOTE:** please consider this is only bug fix for existing applications: we strongly recommend the use of newer applications based on more recent HW whenever it is possible.

For any occurrence do not hesitate to contact: Enrico Boscaro ([enrico.boscaro@carel.com](mailto:enrico.boscaro@carel.com)) or [1tool@carel.com](mailto:1tool@carel.com)

Best regards