

FCS series three-phase fan speed controller / FCS серия трех- фазных регуляторов скорости вентилятора

CAREL

FCS IP55




FCS IP20




FCS controller dimensions (mm) / Размеры контроллера FCS (мм)

FCS IP55



FCS IP20



| Models Модели | 230Vac on request 230В по запросу | A | B | C | D | E | F | IP |
|----------------------------|--------------------------------------|-----|-----|-----|-----|---|----|----|
| FCS3064000 (FCS3062300) | 153 | 133 | 225 | 200 | 115 | 6 | 55 | |
| FCS3124000 (FCS3122300) | 205 | 180 | 280 | 255 | 130 | 6 | 55 | |
| FCS3204000 (FCS3202300) | 198 | 174 | 280 | 255 | 158 | 6 | 55 | |
| FCS3404000 (FCS3402300) | 245 | 219 | 340 | 315 | 200 | 6 | 55 | |
| FCS3094010 (FCS3092310) | 170 | 144 | 265 | 250 | 115 | 6 | 20 | |
| FCS3124010 (FCS3122310) | 170 | 144 | 265 | 250 | 115 | 6 | 20 | |
| FCS3204010 (FCS3202310) | 198 | 174 | 265 | 250 | 140 | 6 | 20 | |
| FCS3404010 (FCS3402310) | 198 | 174 | 265 | 250 | 175 | 6 | 20 | |

Installing FCS / Монтаж FCS




Fig. 2

ENG

Thank you for your choice. We trust you will be satisfied with your purchase.

General characteristics

The FCS series equipment are three-phase electronic voltage controllers that use the phase-cutting principle in order to regulate the output voltage supplied on the load, as a function of the driving signal being applied to the input. They can drive asynchronous electric motors connected for example to fans, pumps, mixers, stirrers etc. There are seven available models, each of them characterized by its own max. load value that can be controlled-

| 3-phase mod. | Rated current | Derating between 40 and 50°C | Peak current | Power dissipated |
|---------------------------|---------------|------------------------------|--------------|------------------|
| FCS3064000 (*2300 230Vac) | 6 A | 5 A | 3 x Rated C | 35 W |
| FCS3124000 (*2300 230Vac) | 12 A | 10 A | 3 x Rated C | 6 W |
| FCS3204000 (*2300 230Vac) | 20 A | 16 A | 3 x Rated C | 128 W |
| FCS3404000 (*2300 230Vac) | 40 A | 32 A | 3 x Rated C | 238 W |
| FCS3094010 (*2310 230Vac) | 9 A | 7 A | 3 x Rated C | 55 W |
| FCS3124010 (*2310 230Vac) | 12 A | 10 A | 3 x Rated C | 65 W |
| FCS3204010 (*2310 230Vac) | 20 A | 16 A | 3 x Rated C | 128 W |
| FCS3404010 (*2310 230Vac) | 40 A | 32 A | 3 x Rated C | 250 W |

They are:

Installing the controller in the electrical panel

It is advisable to install the regulator vertically (see figure 2), in environments where the temperature does not exceed 50°C and the air circulation is suitable, in order to optimize the disposal of the heat that is being produced. For temperatures over 40°C, refer to the above table.

Description of the controller and electrical connections

The controller contains two cards: a lower card with the "power" component and a top one with the driving component. In the "power" card you must connect the three-phase supply and the earth connection to the L1, L2, L3 and PE terminals. In the same way, you must connect the load to the U, V, W, + terminals (Fig. 4a, b). On the driving card you must connect the 0 to 10Vdc (for FCM, pCO and pCO² controllers) or PWM (for μchiller controllers) input signals to the IN-, IN+, G0- terminals (Fig. 3a, c). A 10K potentiometer can also be connected to terminals IN-, IN+ and G+ for manual control (Fig. 3b).

Warnings:

- All the connections and the hardware settings must be carried out by qualified personnel and when the device is not inlet powered.
- In the IP20 version, a red LED placed on the top card and marked 'power' indicates that power is connected, while in the IP55 version the LED is not visible as it is located inside the unit.
- Before supplying the device, you must check that the cables have been connected correctly and close the protection cover.
- It is recommended to verify the suitability of the motors to be used with the phase cutting control.
- In case of fall of the motor revolutions when the input signal increases, it is suggested to act on the MAX. speed potentiometer. The R1, R2, R3 trimmers have already been calibrated by the manufacturer and must not be modified.

The default settings are: MIN: 50 Vrms (29 Vrms), MAX: 390 Vrms (220 Vrms), THRESHOLD: 9.5 Vdc (mode 10 Vdc); 4.75 Vdc (mode PWM), LINEAR: 10 V, CUT-OFF: 50 Hz

- The output cable to the load must be shielded.**Set-up**

With the use of evolved controllers such as pCO, pCO², FCM for the control of the output, it is strictly necessary to use the parameters available via software and leave out the potentiometers placed on the control board. Before supplying with power the controller, it is necessary to program the controller power supply frequency using a proper 60 Hz/50 Hz jumper JP13 placed on the control board (fig. 5a, b, c). In case of power supply frequencies equal to 50 Hz, the jumper has to be placed on the right of the pin-strip; in case of power supply frequencies equal to 60 Hz, the jumper has to be placed on the left of the pin-strip (as indicated by the silk-screen placed on the printed circuit). In case the FCS is controlled by a general controller with control output 0 to 10 Vdc, however it is possible to set some operating parameters on the top board through the auxiliary trimmers and jumpers.

The parameters that can be set with the trimmers are:

- Minimum speed "MIN".
- Maximum speed "MAX".
- Release threshold at maximum "THRESHOLD".

The parameters that can be set with the jumpers are:

- 0-10Vdc input or PWM from μCH input "10V/μCH".
- CUT-OFF or MIN. mode "CUT-OFF/MIN".
- Linear or quadratic input/output relation "LIN/QUAD".

When by mistake the hardware settings on the top board are modified and the FCS acts as slave to FCM, the hardware modifications prevail over the FCM settings.

Linear regulation: In this case each variation of the input signal corresponds, proportionally, to a constant variation of the voltage supplied to the load. In practical terms this means that significant changes in speed will be performed at low driving signal values, with however little variation at higher values.

Minimum speed: Turning the MIN. trimmer clockwise, at the minimum input signal (0 V), the minimum output voltage increases from 50 (29) to about 200 V (115 V).

Maximum speed: Turning the MAX. trimmer anti-clockwise, at the maximum input signal (10 V), the maximum output voltage decreases from 400 V (230 V) to about 300 V (172 V).

RUS

Спасибо за Ваш выбор. Мы надеемся что Вы останетесь довольны приобретением.

Основные характеристики

Однофазный контроллер FCS это электронный регулятор напряжения с использованием принципа контроля фаз и регулированием выходного напряжения в зависимости от входящего сигнала. Контроллер используется для управления асинхронными двигателями, такими как вентиляторы, насосы, смесители, мешалки и т.д. Доступны семь моделей, каждая из которых характеризуется определенным значением максимального рабочего тока, которые могут контролироваться-

| 3x фазная модель | Рабочий ток | Потеря мощности при 40 и 50°C | Пиковый ток | Потребляемая мощность |
|---------------------------|-------------|-------------------------------|---------------------|-----------------------|
| FCS3064000 (*2300 230Vac) | 6 A | 5 A | 3 x кратный рабочий | 35 W |
| FCS3124000 (*2300 230Vac) | 12 A | 10 A | 3 x кратный рабочий | 6 W |
| FCS3204000 (*2300 230Vac) | 20 A | 16 A | 3 x кратный рабочий | 128 W |
| FCS3404000 (*2300 230Vac) | 40 A | 32 A | 3 x кратный рабочий | 238 W |
| FCS3094010 (*2310 230Vac) | 9 A | 7 A | 3 x кратный рабочий | 55 W |
| FCS3124010 (*2310 230Vac) | 12 A | 10 A | 3 x кратный рабочий | 65 W |
| FCS3204010 (*2310 230Vac) | 20 A | 16 A | 3 x кратный рабочий | 128 W |
| FCS3404010 (*2310 230Vac) | 40 A | 32 A | 3 x кратный рабочий | 250 W |

Такие как:

Установка контроллера

Рекомендуется установка контроллера вертикально (см.рис 2) в местах, где температура не превышает 50°C, и циркуляция воздуха, достаточная для удаления выделяемого тепла. Для температур выше 40 °C обратитесь к выше приведенной таблице.

Описание и электрические подключения контроллера

Контроллер состоит из двух электромонтажных плат: «нижняя» с силовыми компонентами и «верхняя» с компонентами управления. К клеммам L1, L2, L3, PE подключается трехфазное напряжение питания и заземление соответственно. Таким же образом подключается нагрузка к клеммам U, V, W (см. рис. 4a, b). К плате управления необходимо подключить управляющий сигнал 0-10V (для контроллеров серии FCM, pCO, pCO²) или PWM (для контроллеров μchiller) на клеммы IN-, IN+, G0 (см. рис. 3a, c). Для ручного регулирования возможно подключение переменного резистора 10kΩ на клеммы IN-, IN+, G0 (см. рис. 3b).

Внимание:

- Все подключения и настройки контроллера должны производиться квалифицированным персоналом при отключенном напряжении питания.
- На версии IP20 красный светодиод, расположенный в верхней части контроллера с маркировкой «power» показывает наличие входного напряжения питания, а на версии IP55 этот светодиод расположен под крышкой и не видим.
- Перед включением напряжения питания контроллера проверьте правильность подключения кабелей и закройте защитную крышку.
- Рекомендуется проверить возможность работы электродвигателя с фазным регулированием.
- В случае, когда скорость вращения электродвигателя снижается при увеличении сигнала регулирования это действие вызвано переменным резистором MAX устанавливающим максимальную скорость вращения. Настройки переменных резисторы R1, R2, R3 отрегулированы изготовителем и не могут быть изменены.

Заводские значения настроек: MIN (минимум) ~50B (29B), MAX (максимум) ~390B (220B) THRESHOLD (порог) 9,5B (режим -10B), -4,75B (режим PWM), LINEAR (линейный) 10B, CUT-OFF(отключение) 50Гц

- Кабель подключения нагрузки должен быть защищен.**Настройка**

При использовании совместно с контроллерами серий pCO, pCO² и FCM для управления выходом необходимо использовать параметры доступные в программном обеспечении контроллеров управления и переменные резисторы на панели регулятора скорости. Перед включением напряжения питания необходимо выставить используемое значение частоты сети 50Гц/60Гц при помощи перемычки JP13 на панели регулятора (см. рис. 5a,b,c). В случае если частота сети 60Гц перемычка устанавливается справа, клеммной колодки , если частота сети 60Гц перемычка устанавливается слева (согласно печати на плате). В случае если FCS управляет основным контроллером с выходом -0 -10B доступны настройки рабочих параметров посредством перемычек и дополнительных переменных резисторов, расположенных в верхней части платы.

Параметры с возможностью регулирования переменными резисторами:

- Минимальная скорость «MIN»
- Максимальная скорость «MAX»
- Изменение порога от максимума «THRESHOLD»

Параметры с возможностью регулирования перемычками:

- вход 0-10B или PWM для μCH вход <10V/μCH>
- режим выключение или минимальная скорость «CUT-OFF/MIN»
- линейный или квадратичный вход/выход «LIN/QUAD»

В случае использования регулятора в качестве «ведомого» для FCM ошибки в настройке на регуляторе имеют преобладающее значение над значениями настроек FCM.

Линейное регулирование: в этом случае изменение входящего сигнала пропорционально изменению выходного напряжения. Практически это значит что значительные изменения скорости будут при низких значениях входящего сигнала и незначительные при высоких.

Минимальная скорость: Регулированием переменного резистора MIN по часовой стрелке, при входящем сигнале (0B), можно изменить выходное напряжение от 50(29) до 200B(115B)

Максимальная скорость: Регулированием переменного резистора MAX против часовой стрелки, при входящем сигнале (10B), можно изменить выходное напряжение от 400(230) до 300B(172B)

