





A	B	C	D	
1	S359-0026	833	242	4/5
2	S359-0027	1461	415	4/5
3	S359-0028	1461	415	4/5
4	S359-1034	1872	595	1/5
5	S359-1035	1872	595	1/5
6	S359-1036	300	575	2/5
7	S359-1037	300	575	2/5
8	S359-2013	1020	628	2/5
9	S359-3016-01	966	595	2/5
10	S359-3017	966	575	2/5
11	S359-5015	999	80	3/5













A	B	C	D	
12	S359-5016	999	80	3/5
13	S359-5028	1712	80	3/5
14	S359-5029	1712	80	3/5
15	S359-911	499	798	2/5
16	S359-9512	1869	488	1/5
17	S359-9513	1869	488	1/5
18	LH-1855	1855	14	1/5
19	S359-564	500	180	2/5
20	S359-565	500	180	2/5
21	S359-562	783	180	2/5
22	DR-961	961	30	2/5








6x a132	2x a133	6x b43	4x c415	12x d37	6x e1	12x e2	8x e3	4x e32
12x e58	24x f1	4x j30	4x k125	10x l1	14x l2	2x n1	1x n26\1	2x p1
2x p25	49x p38	12x p51	8x p93	20x r1	20x r16	4x r36	4x r37	12x s2
1x t17	2x w203 ¹	2x w203 ²	1x z1					

1




§2




2




3








4






5




6



7



8



9

