





A	B		C		D	A		B		C		D
1	S163 0050	1960	491		4/4	9	S163 3322	509	539		3/4	
2	S163 0052	1960	491		4/4	10	S163 3350	2049	539		2/4	
3	S163 1163	2192	580		1/4	11	S163 4440	2013	60		2/4	
4	S163 1164	2192	580		1/4	12	S163 552	1944	29		1/4	
5	S163 1161	1967	539		2/4	13	S163 540	2013	64		2/4	
6	S163 3351	2049	539		2/4	14	S163 9932	1991	505		1/4	
7	S163 3352	993	534		3/4	15	S163 9931	1991	533		1/4	
8	S163 3321	510	539		3/4	16	dr 989	989	30		1/4	
						17	S163 1162	1967	539		2/4	
						18	S163 0053	1960	491		4/4	
						19	Lh 1961	1961	14		1/4	



8x a43	8x a68	8x b18	8x b19	2x c333	24x d1	6x e1	4x j1	4x k1
2x k3813	2x k3815	150x l1	2x n158	2x p1	12x s2	4x n56	8x p27	1x z1
32x p51	20x p38	34x e2	34x f1	38x r1	38x r16	1x Z100	2x p54	


1

§2






2

§6



3





6

